



NHTSA Recall Number 12T-019

Date: July 26, 2012

Subject: SAFETY RECALL NOTICE

Dear Uniroyal Tire Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Uniroyal[®], a brand owned and operated by Michelin North America, Inc., has decided that a defect which relates to motor vehicle safety exists in certain Uniroyal Laredo[®] HD/H[™] brand replacement tires and they are included in a recall of approximately 800,000 tires from the U.S. market. These tires are typically found on commercial light trucks and full size heavy duty vans.

You are receiving this letter because our records indicate that you may have purchased one or more of the recalled tires. It is possible that any one of the tires being recalled may experience tread loss and/or rapid air loss resulting from tread belt separation. This condition may increase the risk of a vehicle crash.

The following list provides the product descriptions, DOT (Department of Transportation) sequence identifiers and DOT production periods of the recalled tires. This DOT information is molded into the sidewall of each tire. The four dashes at the end of the DOT sequence correspond to the DOT date code that is a 2-digit week and 2-digit year of production, which are given in the DOT production period information. For example, "4305" refers to the 43rd week of the year 2005.

Tire description	DOT sequence	DOT production periods (inclusive)
LT235/85 R16 120Q LRE Uniroyal Laredo HD/H	BF0R JDUU - - - -	1310 to 2912
LT245/75 R16 120Q LRE Uniroyal Laredo HD/H	BE11 JDUU - - - - BF11 JDUU - - - -	1310 to 0312 1311 to 5211

Tires matching these descriptions and DOT sequence identifiers, but produced outside of the identified DOT production time periods, are **not** part of this recall. To determine if you have received tires that are included in this recall, please check the DOT information found on the sidewall of the tire as explained on page 4 of this letter.

It is important that all recalled tires be removed from service as soon as possible. The removed tires will be replaced with a similar product at no cost to you.